

Conversion Chart

Inches	Decimal	Points	MM
1/64	0.0156	1.125	0.397
1/32	0.0312	2.25	0.794
3/64	0.0468	3.375	1.191
1/16	0.0625	4.5	1.588
5/64	0.0781	5.625	1.984
3/32	0.0937	6.75	2.381
7/64	0.1093	7.875	2.778
1/8	0.1250	9	3.175
9/64	0.1406	10.125	3.572
5/32	0.1562	11.25	3.969
11/64	0.1718	12.375	4.366
3/16	0.1875	13.5	4.763
13/64	0.2031	14.625	5.159
7/32	0.2187	15.75	5.556
15/64	0.2343	16.875	5.953
1/4	0.2500	18	6.350
17/64	0.2656	19.125	6.747
9/32	0.2812	20.25	7.144
19/64	0.2968	21.375	7.541
5/16	0.3125	22.5	7.938
21/64	0.3281	23.625	8.334
11/32	0.3437	24.75	8.731
23/64	0.3593	25.875	9.128
3/8	0.3750	27	9.525
25/64	0.3906	28.125	9.922
13/32	0.4062	29.25	10.319
27/64	0.4218	30.375	10.716
7/16	0.4375	31.5	11.113
29/64	0.4531	32.625	11.509
15/32	0.4687	33.75	11.906
31/64	0.4843	34.875	12.303
1/2	0.5000	36	12.700

Inches	Decimal	Points	MM
33/64	0.5156	37.125	13.097
17/32	0.5312	38.25	13.494
35/64	0.5468	39.375	13.891
9/16	0.5625	40.5	14.288
37/64	0.5781	41.625	14.684
19/32	0.5937	42.75	15.081
39/64	0.6093	43.875	15.478
5/8	0.6250	45	15.875
41/64	0.6406	46.125	16.272
21/32	0.6562	47.25	16.669
43/64	0.6718	48.375	17.066
11/16	0.6875	49.5	17.463
45/64	0.7031	50.625	17.859
23/32	0.7187	51.75	18.256
47/64	0.7343	52.875	18.653
3/4	0.7500	54	19.050
49/64	0.7656	55.125	19.447
25/32	0.7812	56.25	19.844
51/64	0.7968	57.375	20.241
13/16	0.8125	58.5	20.638
53/64	0.8281	59.625	21.034
27/32	0.8437	60.75	21.431
55/64	0.8593	61.875	21.828
7/8	0.8750	63	22.225
57/64	0.8906	64.125	22.622
29/32	0.9062	65.25	23.019
59/64	0.9218	66.375	23.416
15/16	0.9375	67.5	23.813
61/64	0.9531	68.625	24.209
31/32	0.9687	69.75	24.606
63/64	0.9843	70.875	25.003
1	1.0000	72	25.400